To: Williams, Mike[Mike.Williams@tetratech.com]

From: McCoy, Erin

Sent: Mon 4/18/2016 6:11:26 PM Subject: Information for Task 1

1993 Summary of buildings 1 through 3.pdf

1996 FS for OU4.pdf

1992 OU4 EE Report (building sampling).pdf

Attached is the original FS Report, as well as a few others that may be helpful for Task 1 at the Dico Superfund Site. We need costs associated with completely removing the buildings on site. It would probably be better to have a building by building cost if possible. This would be for buildings 1, 2, 3, maintenance building, and the production building. Buildings 4 & 5 were already removed, however the foundations are still in place, so we'd need costs to remove those as well. No samples were collected in the production building previously, so assume the same general level of contamination. Please let me know if you have any questions. Thanks!



Erin McCoy, P.G. | Remedial Project Manager

**EPA Region 7** | Superfund Division | Iowa Nebraska Branch

11201 Renner Blvd | Lenexa, KS 66219

Phone: 913.551.7977

mccoy.erin@epa.gov | www.epa.gov